

$f_{cd}' = 110 \text{ daN/cm}^2$			$f_{sd} = 3304 - 3826 \text{ daN/cm}^2$			$d'/h = 0.10$				
$\xi = y_c/h$	$\rho = 0$		$\rho = 0.25$		$\rho = 0.50$		$\rho = 0.75$		$\rho = 1.00$	
	r_u	ζ	r_u	ζ	r_u	ζ	r_u	ζ	r_u	ζ
0.100	0.4605	0.8645	0.4605	0.8645	0.4605	0.8645	0.4605	0.8645	0.4605	0.8645
0.110	0.4234	0.8606	0.4194	0.8593	0.4154	0.8581	0.4113	0.8569	0.4071	0.8557
0.120	0.3928	0.8566	0.3852	0.8542	0.3775	0.8519	0.3695	0.8496	0.3613	0.8473
0.130	0.3674	0.8524	0.3565	0.8492	0.3452	0.8459	0.3334	0.8427	0.3211	0.8394
0.140	0.3460	0.8482	0.3320	0.8441	0.3172	0.8401	0.3016	0.8361	0.2850	0.8321
0.150	0.3279	0.8437	0.3109	0.8391	0.2927	0.8345	0.2731	0.8298	0.2517	0.8252
0.160	0.3125	0.8392	0.2926	0.8341	0.2709	0.8291	0.2470	0.8240	0.2203	0.8190
0.170	0.2993	0.8345	0.2765	0.8292	0.2512	0.8240	0.2227	0.8187	0.1895	0.8135
0.180	0.2878	0.8296	0.2620	0.8244	0.2330	0.8192	0.1993	0.8139	0.1580	0.8087
0.190	0.2777	0.8247	0.2489	0.8198	0.2159	0.8148	0.1763	0.8098	0.1239	0.8048
0.200	0.2686	0.8198	0.2368	0.8153	0.1996	0.8108	0.1530	0.8063	0.0824	0.8018
0.209	0.2615	0.8154	0.2270	0.8115	0.1858	0.8077	0.1317	0.8038	0	0
0.210	0.2606	0.8148	0.2262	0.8111	0.1851	0.8074	0.1312	0.8037	0	0
0.220	0.2533	0.8097	0.2197	0.8073	0.1796	0.8049	0.1272	0.8024	0	0
0.230	0.2466	0.8046	0.2138	0.8035	0.1747	0.8023	0.1236	0.8012	0	0
0.240	0.2416	0.8002	0.2092	0.8001	0.1708	0.8001	0.1208	0.8000	0	0
0.250	0.2373	0.7960	0.2054	0.7970	0.1676	0.7980	0.1184	0.7990	0	0
0.275	0.2277	0.7856	0.1968	0.7892	0.1603	0.7928	0.1131	0.7964	0	0
0.300	0.2195	0.7752	0.1893	0.7814	0.1540	0.7876	0.1085	0.7938	0	0
0.325	0.2123	0.7648	0.1828	0.7736	0.1484	0.7824	0.1044	0.7912	0	0
0.350	0.2060	0.7544	0.1771	0.7658	0.1435	0.7772	0.1007	0.7886	0	0
0.375	0.2004	0.7440	0.1720	0.7580	0.1391	0.7720	0.0975	0.7860	0	0
0.400	0.1954	0.7336	0.1674	0.7502	0.1352	0.7668	0.0946	0.7834	0	0
0.425	0.1909	0.7232	0.1632	0.7424	0.1316	0.7616	0.0919	0.7808	0	0
0.450	0.1869	0.7128	0.1594	0.7346	0.1283	0.7564	0.0894	0.7782	0	0
0.475	0.1833	0.7024	0.1560	0.7268	0.1253	0.7512	0.0872	0.7756	0	0
0.500	0.1800	0.6920	0.1529	0.7190	0.1226	0.7460	0.0851	0.7730	0	0
0.525	0.1770	0.6816	0.1500	0.7112	0.1200	0.7408	0.0832	0.7704	0	0
0.550	0.1742	0.6712	0.1474	0.7034	0.1177	0.7356	0.0814	0.7678	0	0
0.575	0.1717	0.6608	0.1450	0.6956	0.1155	0.7304	0.0798	0.7652	0	0
0.600	0.1695	0.6504	0.1427	0.6878	0.1135	0.7252	0.0782	0.7626	0	0
0.621	0.1677	0.6417	0.1410	0.6813	0.1119	0.7209	0.0770	0.7604	0	0